
METALEARTH


3D LASER CUT MODELS



It is highly recommended that you visit www.fascinations.com/metalearth360/mms003 to see the completed model before assembling your own








Fold

Insertion lines can tabs are inserted be seen and then as shown folded



Metal sheet


To create the best connections




Insert tab and bend 90 degrees for most visible areas



Insert tab and twist 90 degrees is best in some areas to ensure a tight connection







In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

