


METAL EARTH™


3D LASER CUT MODELS



It is highly recommended that you visit
www.fascinations.com/metalearth360/mms051
 to see the completed model before assembling your own




mms051



Insertion tabs are inserted and then folded

Fold lines can be seen as shown here

Insertion holes




Needle nose pliers are helpful for assembly



To create the best connections

● Insert tab and bend 90 degrees for most visible areas

▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Metal sheet



Assembly Flow Chart

