

## METAL EARTH 3D LASER CUT MODELS It is highly recommended that you visit www.fascinations.com/metalearth360/mms080 to see the completed model before assembling your own mms080 To create the best connections Insert tab and bend 90 degrees for most visible areas Insert tab and twist 90 degrees is best in some areas to ensure Needle nose pliers are helpful for assembly a tight connection Insertion Fold Insertion holes lines can tabs are Pull and Screw metal tab 90° to tighten inserted be seen as shown and then folded here Metal sheets



In order to avoid possible injury from sharp edges, please carefully

discard the metal sheet after parts have been removed



6

