



METAL EARTH™

3D LASER CUT MODELS




It is highly recommended that you visit
www.fascinations.com/metalearth360/mms204
 to see the completed model before assembling your own



Insertion tabs are inserted and then folded

Insertion holes

Fold lines can be seen as shown here




Needle nose pliers are helpful for assembly


To create the best connections

Insert tab and bend 90 degrees for most visible areas


Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed



Assembly Flow Chart



Assembly Flow Chart

